

10/10/2007

ALLENDALE County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
ALLENDALE County					
ALLENDALE MAINTENANCE FACILITY	PETRO	UST	BLWM		Site ID #00316. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaits)
ALLENS GARAGE	PETRO	UST	BLWM		Site ID #12939. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits)
BASF	VOC	S/L	BOW		In remediation.
BILLS EXXON STATION	PETRO	UST	BLWM		Site ID #00307. RBCA Classification 3BF5. Inactive.
BILLS SERVICE CENTER	PETRO	UST	BLWM		Site ID #12488. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaits)
BRIDGES CITGO STATION	PETRO	UST	BLWM		Site ID #00329. RBCA Classification 3BF5. Inactive.
BURTS FAST STOP	PETRO	UST	BLWM		Site ID #15764. RBCA Classification 2BB3. Monitored Natural Attenuation (MNA).
CHOICE CUTS MEATS & SEAFOOD	PETRO	UST	BLWM		Site ID #00306. RBCA Classification 3BF8. Awaiting Funding.
CONNELLY TEXACO	PETRO	UST	BLWM		Site ID #14780. RBCA Classification 2BB8. Awaiting Funding.
CORBETT PLYWOOD COMPANY	PETRO	UST	BLWM		Site ID #17996. RBCA Classification 2BB3. Monitored Natural Attenuation (MNA).
DR R E BOYLES	PETRO	UST	BLWM		Site ID #16416. RBCA Classification 3BF8. Awaiting Funding.
FAIRFAX TOWN OF	PETRO	UST	BLWM		Site ID #16451. RBCA Classification 1A4. Active Corrective Action.
FIRESTONE HOME & AUTO	PETRO	UST	BLWM		Site ID #00321. RBCA Classification 2BB5. Inactive.
FLEETWOOD ONE STOP	PETRO	UST	BLWM		Site ID #00327. RBCA Classification 5A1. Conducting Investigation/Risk Assessment.
FORMER SPEAKS OIL SITE	PETRO	AGT	BOW		In assessment phase.
H&S SERVICE STATION	PETRO	UST	BLWM		Site ID #00304. RBCA Classification 3BF6. Contacted.
HELENA CHEMICAL CO. - FAIRFAX	METALS, PEST/HERB	LF	BLWM	SCD058753971	BLWM File # 51560. In monitoring and remediation phases. Plume is discharging to unnamed wetland.
INTERSTATE TRUCK TERMINAL INC	PETRO	UST	BLWM		Site ID #00332. RBCA Classification 2BB1. Conducting Investigation/Risk Assessment.
M&M VARIETY	PETRO	UST	BLWM		Site ID #00322. RBCA Classification 3BF6. Contacted.
MANUELS GROCERY	PETRO	UST	BLWM		Site ID #15829. RBCA Classification 2AA8. Awaiting Funding.
MILLPOND GROCERY	PETRO	UST	BLWM		Site ID #00312. RBCA Classification 3BA8. Awaiting Funding.

10/10/2007

ALLENDALE County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
POLITES MOBIL	PETRO	UST	BLWM		Site ID #00314. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaits
SMARTS CITGO	PETRO	UST	BLWM		Site ID #00328. RBCA Classification 4BC8. Awaiting Funding.
STOP AND GO	PETRO	UST	BLWM		Site ID #00331. RBCA Classification 5A8. Awaiting Funding.
STOP N GO 2	PETRO	UST	BLWM		Site ID #11126. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits
THREE WAY FOOD MART 2	PETRO	UST	BLWM		Site ID #00324. RBCA Classification 2BB3. Monitored Natural Attenuation (MNA).
US 301 & BAY ST SITE SE	PETRO	UST	BLWM		Site ID #18668. RBCA Classification 5A1. Conducting Investigation/Risk Assessment.
WHATLEY CHEVROLET INC	PETRO	UST	BLWM		Site ID #00303. RBCA Classification 4BC5. Inactive.
WHITLOCK WOOL COMBING CO., INC	NO3	SI	BOW		In recovery phase.
Total for ALLENDALE					29